



Item No.	D	d	l	L	Stock		
					M	MPC	MNF
SC41	2.5	3	11	38	●	●	
SC42	3	3	14	38	●	●	
SC42 - L2	3	3	14	50	○	○	
SC42 - L3	3	3	14	75	○	○	
SC51	6.3	3	12.7	50	○	●	
SC52	4	3	12.7	38	●	●	
SC53	5	3	12.7	38	●	●	
SC11	3	6	12	56	●	○	
SC13	4	6	16	50	●	○	
SC14	5	6	16	50	●	○	
SC1	6	6	16	50	●	○	●
SC1 - L	6	6	25	50	○	○	
SC2	8	6	19	63	●	○	
SC3	9.5	6	19	63	●	○	●
SC3 - L	9.5	6	25	69	○	○	
SC4	11	6	25	69	●	○	
SC5	12.7	6	25	69	●	○	●
SC6	16	6	25	69	●	○	○
SC7	19	6	25	69	●	○	○
SC9	25	6	25	69	●	○	

MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу

● stock standard ○ non-standard stock ■ stock exhaustion



Always wear goggles when using the rotary burrs  
 Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi  
 Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen  
 Toujours porter les lunettes de sécurité en utilisant les limes rotatives  
 Para usar las limas rotativas es obligatorio usar gafas de protección  
 При работе с борфрезами всегда используйте защитные очки