



Item No.	D	d	l	L	Stock	Stock	Stock
SE41	3	3	5.5	38	●	●	
SE41 - L2	3	3	5.5	50	○	●	
SE41 - L3	3	3	5.5	75	○	●	
SE51	6.3	3	9.5	47	●	●	
SE53	5	3	7.1	38	●	●	
SE1	6	6	9.5	50	●	○	
SE3	9.5	6	16	60	●	○	○
SE5	12.7	6	22	66	●	○	○
SE6	16	6	25	69	●	○	○
SE7	19	6	25	69	●	○	○

MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу ● stock standard ○ non-standard stock ■ stock exhaustion



Always wear goggles when using the rotary burrs Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi  
 Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen Toujours porter les lunettes de sécurité en utilisant les limes rotatives  
 Para usar las limas rotativas es obligatorio usar gafas de protección При работе с борфрезами всегда используйте защитные очки