





Item No.	D	d	l	L	α	M	MPC	MNF	Stock	Stock	Stock
SJ42	3	3	2.5	38	60°				○	●	
SJ1	6	6	4	50	60°				●	○	
SJ3	9.5	6	8	55	60°				●	○	
SJ5	12.7	6	11	58	60°				●	○	
SJ6	16	6	13.5	61	60°				●	○	
SJ7	19	6	16.5	65	60°				○	○	
SJ9	25	6	21.5	68	60°				○	○	



MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу ● stock standard ○ non-standard stock ■ stock exhaustion



Always wear goggles when using the rotary burrs Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi
 Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen Toujours porter les lunettes de sécurité en utilisant les limes rotatives
 Para usar las limas rotativas es obligatorio usar gafas de protección При работе с борфрезами всегда используйте защитные очки