



Item No.	D	d	l	L	Stock	Stock	Stock
SA41	1.5	3	6	38	●	●	
SA41 - L2	1.5	3	6	50	○	○	
SA41 - L3	1.5	3	6	75	○	○	
SA42	2.5	3	11	38	●	●	
SA42 - L2	2.5	3	11	50	○	○	
SA42 - L3	2.5	3	11	75	○	○	
SA43	3	3	14	38	●	●	
SA43 - L2	3	3	14	50	○	○	
SA43 - L3	3	3	14	75	○	○	
SA52	4	3	12.7	38	●	●	
SA53	5	3	12.7	38	○	●	
SA51	6.3	3	12.7	50	●	●	
SA11	3	6	12	56	●	○	
SA13	4	6	16	50	●	○	
SA14	5	6	16	50	●	○	
SA1	6	6	16	50	○	○	●
SA1 - L	6	6	25	50	○	○	
SA2	8	6	19	63	●	○	
SA3	9.5	6	19	63	●	○	●
SA3 - L	9.5	6	25	69	○	○	
SA4	11	6	25	69	●	○	
SA5	12.7	6	25	69	●	○	●
SA6	16	6	25	69	●	○	○
SA7	19	6	25	69	●	○	○
SA9	25	6	25	69	●	○	

MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу

● stock standard ○ non-standard stock ■ stock exhaustion



Always wear goggles when using the rotary burrs / Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi / Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen / Toujours porter les lunettes de sécurité en utilisant les limes rotatives / Para usar las limas rotativas es obligatorio usar gafas de protección / При работе с борфрезами всегда используйте защитные очки