



Item No.	D	d	l	L	M			MPC			MNF				
					Stock	Stock	Stock	Stock	Stock	Stock	Stock	Stock	Stock		
SB41	1.5	3	6	38	●	●									
SB41 - L2	1.5	3	6	50	○	○									
SB41 - L3	1.5	3	6	75	○	○									
SB42	2.5	3	11	38	○	●									
SB42 - L2	2.5	3	11	50	○	○									
SB42 - L3	2.5	3	11	75	○	○									
SB43	3	3	14	38	●	●									
SB43 - L2	3	3	14	50	○	○									
SB43 - L3	3	3	14	75	○	○									
SB51	6.3	3	4.7	43	●	●									
SB11	3	6	12	56	●	○									
SB13	4	6	16	50	●	○									
SB14	5	6	16	50	●	○									
SB1	6	6	16	50	●	○		○							
SB1 - L	6	6	25	50	○	○									
SB2	8	6	19	63	●	○									
SB3	9.5	6	19	63	●	○		○							
SB3 - L	9.5	6	25	69	○	○									
SB4	11	6	25	69	●	○									
SB5	12.7	6	25	69	●	○		○							
SB6	16	6	25	69	●	○		○							
SB7	19	6	25	69	●	○		○							
SB9	25	6	25	69	●	○									

MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу ● stock standard ○ non-standard stock ■ stock exhaustion



Always wear goggles when using the rotary burrs / Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi / Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen / Toujours porter les lunettes de sécurité en utilisant les limes rotatives / Para usar las limas rotativas es obligatorio usar gafas de protección / При работе с борфрезами всегда используйте защитные очки

TYPHOON
C-SD-TA
LFTA
SUTA
HSS-HSS/CO DRILLS
UH RED
MEX ORANGE
HF EVO
MEF ENDLESS
ALU
MDC
G2
MDTA
ULTRA MILLS
HSS/CO
CARBIDE BURRS
PARAMETERS