


Item No.	D	d	l	L	M	MPC	MNF
					Stock	Stock	Stock
SD41	2.5	3	2.3	38	●	●	
SD42	3	3	2.8	38	●	●	
SD42 - L2	3	3	2.8	50	○	○	
SD42 - L3	3	3	2.8	75	○	○	
SD51	6.3	3	5	44	●	●	
SD53	5	3	4	38	●	●	
SD11	3	6	2.8	50	●	○	
SD14	5	6	4	50	●	○	
SD1	6	6	5	50	●	○	○
SD2	8	6	6.4	50	●	○	
SD3	9.5	6	8	52	●	○	○
SD4	11	6	9.5	54	●	○	
SD5	12.7	6	11	55	●	○	○
SD6	16	6	14	58	●	○	○
SD7	19	6	16	62	●	○	○
SD9	25	6	23	68	●	○	



MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу

● stock standard ○ non-standard stock ■ stock exhaustion



Always wear goggles when using the rotary burrs
 Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi
 Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen
 Toujours porter les lunettes de sécurité en utilisant les limes rotatives
 Para usar las limas rotativas es obligatorio usar gafas de protección
 При работе с борфрезами всегда используйте защитные очки

TYPHOON
 C-SD-TA
 LFTA
 SUTA
 HSS-
HSS/CO
DRILLS
 UH
RED
 MEX
ORANGE
 HF
EVO
 MEF
ENDLESS
 ALU
 MDC
 G2
 MDTA
 ULTRA
MILLS
 HSS/CO
 CARBIDE
BURRS
 PARAMETERS