



Item No.	D	d	l	L	M	MPC	MNF
					Stock	Stock	Stock
SF41	3	3	6	38	○	●	
SF42	3	3	12.7	38	●	●	
SF42 - L2	3	3	12.7	50	○	○	
SF42 - L3	3	3	12.7	75	○	○	
SF51	6.3	3	12.7	50	●	●	
SF53	5	3	12.7	38	●	●	
SF11	3	6	12.7	56	●	○	
SF1	6	6	16	50	●	○	○
SF3	9.5	6	19	63	●	○	○
SF4	11	6	25	69	●	○	
SF13	12.7	6	19	63	○	○	
SF5	12.7	6	25	69	●	○	○
SF6	16	6	25	69	●	○	○
SF7	19	6	25	69	●	○	
SF14	19	6	32	76	○	○	○
SF15	19	6	38	82	○	○	

MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу

● stock standard ○ non-standard stock ■ stock exhaustion



Always wear goggles when using the rotary burrs
 Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi
 Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen
 Toujours porter les lunettes de sécurité en utilisant les limes rotatives
 Para usar las limas rotativas es obligatorio usar gafas de protección
 При работе с борфрезами всегда используйте защитные очки

TYPHOON
 C-SD-TA
 LFTA
 SUTA
 HSS-HSS/CO DRILLS
 UH RED
 MEX ORANGE
 HF EVO
 MEF ENDLESS
 ALU
 MDC
 G2
 MDTA
 ULTRA MILLS
 HSS/CO
 CARBIDE BURRS
 PARAMETERS