



Item No.	D	d	l	L	Stock	Stock	Stock
SG41	3	3	6	38	●	●	
SG43	3	3	9.5	38	●	●	
SG44	3	3	12.7	38	●	●	
SG44 - L2	3	3	12.7	50	○	○	
SG44 - L3	3	3	12.7	75	○	●	
SG51	6.3	3	12.7	50	●	●	
SG53	5	3	12.7	38	●	●	
SG1	6	6	16	50	●	○	
SG2	8	6	19	63	●	○	
SG3	9.5	6	19	63	●	○	
SG13	12.7	6	19	63	○	○	
SG5	12.7	6	25	69	●	○	
SG6	16	6	25	69	●	○	
SG7	19	6	25	69	●	○	
SG15	19	6	38	82	○	○	

MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу
 ● stock standard
○ non-standard stock
■ stock exhaustion



⚠ Always wear goggles when using the rotary burrs ✔ Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi
 ⚠ Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen ✔ Toujours porter les lunettes de sécurité en utilisant les limes rotatives
 ⚠ Para usar las limas rotativas es obligatorio usar gafas de protección ✔ При работе с борфрезами всегда используйте защитные очки