


Item No.	D	d	l	L	α	M	MPC	MNF	Stock	Stock	Stock
SK42	3	3	1.5	38	90°	○	●				
SK1	6	6	3	50	90°	●	○				
SK3	9.5	6	4.7	52	90°	●	○				
SK5	12.7	6	6.3	54	90°	●	○				
SK6	16	6	8	57	90°	●	○				
SK7	19	6	9.5	58	90°	○	○				
SK9	25	6	12.7	60	90°	○	○				

MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу

● stock standard ○ non-standard stock ■ stock exhaustion



- TYPHOON
- C-SD-TA
- LFTA
- SUTA
- HSS-HSS/CO DRILLS
- UH RED
- MEX ORANGE
- HF EVO
- MEF ENDLESS
- ALU
- MDC
- G2
- MDTA
- ULTRA MILLS
- HSS/CO
- CARBIDE BURRS
- PARAMETERS



Always wear goggles when using the rotary burrs
 Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi
 Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen
 Toujours porter les lunettes de sécurité en utilisant les limes rotatives
 Para usar las limas rotativas es obligatorio usar gafas de protección
 При работе с борфрезами всегда используйте защитные очки