

Item No.	D	d	l	L	α	M	MPC	MNF	Stock	Stock	Stock
SM41	3	3	8.9	38	12°	●	●				
SM42	3	3	11	38	14°	●	●				
SM42 - L2	3	3	11	50	14°	○	○				
SM42 - L3	3	3	11	75	14°	○	○				
SM43	3	3	16	38	7°	●	●				
SM51	6.3	3	12.7	53	22°	●	●				
SM53	5	3	12.7	38	16°	○	●				
SM1	6	6	12.7	50	22°	●	○				
SM2	6	6	19	50	14°	●	○				
SM3	6	6	25	50	10°	●	○				
SM4	9.5	6	16	63	28°	●	○				
SM5	12.7	6	22	69	28°	●	○				
SM6	16	6	25	73	31°	●	○				

MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу

● stock standard ○ non-standard stock ■ stock exhaustion



Always wear goggles when using the rotary burrs **Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi**
 Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen **Toujours porter les lunettes de sécurité en utilisant les limes rotatives**
 Para usar las limas rotativas es obligatorio usar gafas de protección **При работе с борфрезами всегда используйте защитные очки**

TYPHOON
C-SD-TA
LFTA
SUTA
HSS-HSS/CO DRILLS
UH RED
MEX ORANGE
HF EVO
MEF ENDLESS
ALU
MDC
G2
MDTA
ULTRA MILLS
HSS/CO
CARBIDE BURRS
PARAMETERS