



Item No.	D	d	l	L	α	Stock	Stock	Stock
SN41	2.5	3	3	38	10°	●	●	
SN42	3	3	4	38	10°	●	●	
SN51	6.3	3	6	44	10°	○	●	
SN53	5	3	6.3	38	10°	○	●	
SN1	6	6	8	50	10°	●	○	
SN2	9.5	6	9.5	53	13°	●	○	
SN4	12.7	6	12.7	57	28°	●	○	
SN6	16	6	19	63	18°	●	○	
SN7	19	6	16	70	30°	○	○	

MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу

● stock standard ○ non-standard stock ■ stock exhaustion



BUR10 M TYPE

Set 10pcs.

shank Ø6 mm

SA1 - SB1 - SC1 - SD1 - SE1
SF1 - SG1 - SL1 - SM1 - SN1



A15FW MPC TYPE

Set 15pcs.

shank Ø3 mm

SA41 - SA42 - SA43 - SA52 - SB43 - SC42 - SD41
SD42 - SD53 - SE41 - SG43 - SL42 - SM42 - SM43 - SN42

A16FW M TYPE

Set 15pcs.

shank Ø3 mm

SA41 - SA42 - SA43 - SA52 - SB43 - SC42 - SD41
SD42 - SD53 - SE41 - SG43 - SL42 - SM42 - SM43 - SN42



Always wear goggles when using the rotary burrs / Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi
Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen / Toujours porter les lunettes de sécurité en utilisant les limes rotatives
Para usar las limas rotativas es obligatorio usar gafas de protección / При работе с борфрезами всегда используйте защитные очки