

Item No.	D	d	l	L		M	MPC	MNF	Stock	Stock	Stock
SH41	3	3	6.3	38	●	●					
SH41 - L2	3	3	6.3	50	○	○					
SH41 - L3	3	3	6.3	75	○	○					
SH53	5	3	9.5	38	○	●					
SH2	8	6	19	63	●	○					
SH5	12.7	6	32	76	●	○					
SH6	16	6	36	80	●	○					
SH7	19	6	41	85	●	○					

MDC a richiesta · on request · auf Anfrage · sur demande · a petición · по запросу ● stock standard ○ non-standard stock ■ stock exhaustion



Always wear goggles when using the rotary burrs
 Per l'uso delle lime rotative è obbligatorio indossare occhiali protettivi
 Tragen Sie immer die Schutzbrille wenn Sie die Fräser benutzen
 Toujours porter les lunettes de sécurité en utilisant les limes rotatives
 Para usar las limas rotativas es obligatorio usar gafas de protección
 При работе с борфрезами всегда используйте защитные очки

TYPHOON
 C-SD-TA
 LFTA
 SUTA
 HSS-
 HSS/CO
 DRILLS
 UH
 RED
 MEX
 ORANGE
 HF
 EVO
 MEF
 ENDLESS
 ALU
 MDC
 G2
 MDTA
 ULTRA
 MILLS
 HSS/CO
 CARBIDE
 BURRS
 PARAMETERS